



Video:



PHOTOS: Click the link below to view all high resolution images

https://app.aspenfieldservices.com/api/attachments/get/wM8uhT9ayqwChw5sZ/full_report_0026185_wM8uhT9ayqwChw5sZ.pdf?view

NOTE: By clicking above, you will be redirected to Aspen Field Services' website, not a Wells Fargo property.

Inspection Details	
Year	2015
Make	Shuttlewagon
Model	SWX315
Serial Number	31515061
Type	Railcar
Inspection Date	12/4/2020
Location of Business	JJ Kane Auctioneers - 2157 NE Jacksonville Rd , Ocala, FL, 34470, USA
Attachment(s)/ Accessory(s)	None
Enclosed Cab	Yes
Controls	Standard
Hours	1077
Cab A-C	Yes
Cab Heat	Yes
Keyless Start	No
Visual Inspection	Clean



Aspen Field Services

Job #: 26185 /

Serial #: 31515061

For more information, visit:

wellsfargo.com/equipmentseller

2015 SWX315 SHUTTLEWAGON

Inspection Details Cont'd	
Operational Test	Operational
Front Right Tire Part Number	Michelin: Not Available
Front Right Tire Condition	Good Condition
Front Right Tire Depth Measurement	28/32"
Front Right Tire Size	315/80 R 22.5
Front Left Tire Part Number	Michelin: Not Available
Front Left Tire Condition	Good Condition
Front Left Tire Depth Measurement	24/32"
Front Left Tire Size	315/80 R 22.5
Back Right Tire Part Number	Michelin: Not Available
Back Right Tire Condition	Good Condition
Back Right Tire Depth Measurement	27/32"
Back Right Tire Size	315/80 R 22.5
Back Left Tire Part Number	Goodyear: Not Available
Back Left Tire Condition	Good Condition
Back Left Tire Depth Measurement	29/32"
Back Left Tire Size	315/80R22.5
Back Left Drive Hub	Good Condition
Back Right Drive Hub	Good Condition
Front Left Drive Hub	Good Condition
Front Right Drive Hub	Good Condition
Front Coupler Lift Cylinder	Good Condition
Rear Coupler Lift Cylinder	Good Condition
Tailgate Lights	Good Condition
Working Lights	Good Condition
Cab Door	Good Condition
Side Glass Complete	Good Condition
Seat	Good Condition
Muffler	Good Condition
Intake Screen	Good Condition
Engine Compartment	Dirty
Engine MFR	Not Visible
Customer Decals Visible on Unit	No
Air Tank	Good Condition
Backup Camera	No
Mismatched Tires	Yes
Cab A-C Condition	Good Condition
Cab Heat Condition	Good Condition
Comments	

Inspection Details Cont'd

Aspen Field Services



Front / 12-08-2020



Front / 12-03-2020

Aspen Field Services



Rear / 12-03-2020



Seat / 12-03-2020

Aspen Field Services




Rear / 12-03-2020



Serial Number 31515061 / 12-03-2020

Aspen Field Services



Hours 1077 / 12-08-2020



Active Warnings Low Fuel / 12-08-2020

Aspen Field Services



Passenger Seat / 12-03-2020



Controls / 12-03-2020

Aspen Field Services



Key Ignition / 12-03-2020



Steering Wheel / 12-03-2020

Aspen Field Services



Pedals / 12-03-2020



Fan / 12-03-2020

Aspen Field Services



Interior / 12-03-2020



Cab Light / 12-03-2020

Aspen Field Services



HVAC / 12-03-2020



Interior / 12-03-2020

Aspen Field Services



Passenger Door / 12-03-2020



Driver Door / 12-03-2020

Aspen Field Services



Front Glass / 12-03-2020



Left Glass / 12-03-2020

Aspen Field Services



Right Glass / 12-03-2020



Rear Glass / 12-03-2020

Aspen Field Services



Muffler / 12-03-2020

Aspen Field Services



Air Tank / 12-03-2020




Engine Door / 12-08-2020

Aspen Field Services




Engine Door / 12-03-2020



Engine Compartment / 12-03-2020

Aspen Field Services



Engine MFR Not Visible / 12-03-2020



Intake Screen / 12-03-2020

Aspen Field Services



Left Railings / 12-03-2020



Rear Railings / 12-03-2020

Aspen Field Services



Right Railings / 12-03-2020



Front Left Tire Condition / 12-03-2020

Aspen Field Services



Front Left Tire Brand / 12-03-2020

Aspen Field Services



Front Left Tire Size / 12-03-2020

Aspen Field Services



Front Left Tire Tread Depth Measurement / 12-03-2020



Front Left Drive Hub / 12-03-2020

Aspen Field Services



Hoses / 12-03-2020



Back Left Tire Condition / 12-03-2020

Aspen Field Services



Back Left Tire Brand / 12-03-2020



Back Left Tire Size / 12-08-2020

Aspen Field Services



Back Left Tire Tread Depth / 12-08-2020



Back Left Tire Drive Hub / 12-03-2020

Aspen Field Services



Back Right Tire Condition / 12-03-2020



Back Right Tire Brand / 12-03-2020

Aspen Field Services



Back Right Tire Size / 12-03-2020



Back Right Tire Tread Depth / 12-03-2020

Aspen Field Services



Back Right Drive Hub / 12-03-2020



Front Right Tire Condition / 12-03-2020

Aspen Field Services



Front Right Tire Brand / 12-03-2020



Front Right Tire Size / 12-08-2020

Aspen Field Services



Front Right Tire Tread Depth Measurement / 12-03-2020



Front Right Drive Hub / 12-03-2020

Aspen Field Services



Front Coupler Lift Cylinder / 12-03-2020



Rear Coupler Lift Cylinder / 12-03-2020

Aspen Field Services



Front Lights / 12-08-2020



Tail Lights / 12-08-2020

Aspen Field Services



Backup Camera None / 12-08-2020